BUCHANAN SPLICE CAP

COPPER WIRE ONLY

TO INSTALL: Strip wires approximately 3/4" long. Insert wires thru cap and twist. Insert Buchanan C24 or P24 pres-SURE-tool with latch at "B", Squeeze. Cut wires flush after crimping. INSULATE with BUCHANAN #2014 nylon insulator.

TO REMOVE: Snip cap at both ends of one crimp or squeeze alternately 90° apart between crimps.

UL and CSA listed as "pressure cable connectors" for 5-11 #14, 3-7 #12, 2-5 #10, 2-3 #8 2 #6 stranded; 4-10 #14, 3-6 #12, 2-4 #10, 2 #8 solid. Consult factory for complete list of wire combinations.



COPPER WIRE ONLY

TO INSTALL: Strip wires approximately 3/4" long. Insert wires thru cap and twist. Insert Buchanan C24 or P24 pres-SURE-tool with latch at "B", Squeeze. Cut wires flush after crimping. INSULATE with BUCHANAN #2014 nylon insulator.

TO REMOVE: Snip cap at both ends of one crimp or squeeze alternately 90° apart between crimps.

UL and CSA listed as "pressure cable connectors" for 5-11 #14, 3-7 #12, 2-5 #10, 2-3 #8 2 #6 stranded; 4-10 #14, 3-6 #12, 2-4 #10, 2 #8 solid. Consult factory for complete list of wire combinations.





IDEAL INDUSTRIES, INC.
Sycamore, IL 60178, U.S.A.
1075106 AW 101B
Made in U.S.A. of US and global components.







IDEAL INDUSTRIES, INC.
Sycamore, IL 60178, U.S.A.
1075106 AW 101B
Made in U.S.A. of US and global components.

2011SB/500

